




Computer Memory Test Labs Final Report

| <u>MOTHERBOARD</u> | <u>MANUFACTURER</u> | <u>CHIPSET</u> | <u>TEST NUMBER</u> | <u>TEST STATUS</u> | | | | |
|--|---------------------|--|--|--|------------------|------------|---|----------|
| DG965OT | Intel | Intel 965 | 012906 | PASSED | | | | |
| <u>MODULE INFORMATION</u> | | | | <u>Compatibility Ranking Level</u> | | | | |
| Manufacturer Name: Ventura Technology Group Part #: D2-53CD64LV-555 MB: 1GB Config: 128M x 64 DRAM: Elpida DRAM Part #: EDE5108AGBG-6E-E rev G PCB Part: D2U72G na PCB_layer_count: 6 Layer Module Info: Unbuffered | | | Cas Latency: 5 Dual Die Package: <input type="checkbox"/> Env. Code RoHS Bank: 2 Assembly Type: Single Board/Non Stacked DDR2 DIMM | <table border="1" style="margin: auto;"> <tr> <td style="text-align: center;">Certified</td> <td style="text-align: center;">CRL</td> </tr> <tr> <td style="text-align: center;"></td> <td style="text-align: center;">6</td> </tr> </table> | Certified | CRL |  | 6 |
| Certified | CRL | | | | | | | |
|  | 6 | | | | | | | |
| <u>SYSTEM INFORMATION</u> | | <u>TESTING DETAILS</u> | | | | | | |
| <u>MINIMUM SYSTEM INFORMATION</u> Minimum System: DG965OT Serial Number: BQOT63000028 Board Revision: D63733-201 Post Memory Count: 1024 Processor Code: P4 3.6Ghz 800Mhz Bios at time of test: MQ96510J.86A.1545 MCFT Memory Count 1007M Max_HDD_Man: Max_HDD_Cap: Max_HDD_Ser: | | 55°C Temperature: Standard Voltage Start Date: 12/13/2006 Stop Date: 12/14/2006 Insertion Test: Pass SPD Check: Pass MCFT Min: Pass MCFT Max: Pass S3 Test: Pass Power Cycle Test: Pass Power Cycle Time: 28 OS: Windows XP Service Pack: 2 Test Version: MCFT V2.24 | | | | | | |
| <u>MAXIMUM SYSTEM INFORMATION</u> Maximum System: DG965OT Serial Number: BQOT63000033 Board Revision: D63733-201 Post Memory Count: 4096 Processor Code: P4 3.6Ghz 800Mhz Bios at time of test: MQ96510J.86A.1545 MCFT Memory Count 4G 704M Max_HDD_Man: Max_HDD_Cap: Max_HDD_Ser: | | | | | | | | |
| <u>VENDOR CONTACT INFORMATION</u> | | | | | | | | |
| Contact: Sam Lewis | | Contact Phone: (805) 581-0800 | | Purchase Order #: n/a | | | | |
| Test Traveler Notes: | | | CMTL USE ONLY: | | | | | |
| | | | Verified by: | | | | | |
| | | | Emailed by: | | | | | |

Test Technician: Thanh Nguyen

In the event of a module failure, CMTL is not required to provide root cause analysis. Accuracy of testing is restricted to the above mentioned module with specific DRAM, PCB and other components as listed and tested with the CMTL Memory Compatibility Functionality Test, Microsoft Advanced Server 2000®, Windows NT 4.0 Enterprise Edition®, Windows XP®, Windows 98 SE®, Dos 6.22®, MSTRESS® (v x.xx), XLINEAR® (v x.xx), FXLINEAR® (v x.xx), Patin® (v x.x), WinMTA® (v x.xx). (Voltage margining applied only to those systems that are applicable.)

WWW.CMTLABS.COM