




Computer Memory Test Labs Final Report

<u>MOTHERBOARD</u>	<u>MANUFACTURER</u>	<u>CHIPSET</u>	<u>TEST NUMBER</u>	<u>TEST STATUS</u>			
DX48BT2	Intel	Intel® X48	017134	PASSED			
MODULE INFORMATION				Compatibility Ranking Level			
Manufacturer Name: Kingston		Module ID: KIN287		<table border="1" style="width: 100%;"> <tr> <td style="text-align: center;">Certified CRL</td> </tr> <tr> <td style="text-align: center;">  </td> </tr> <tr> <td style="text-align: center;">6</td> </tr> </table>	Certified CRL		6
Certified CRL							
							
6							
Part #: KVR1333D3N9/2G		Cas Latency: 9					
MB: 2GB		Dual Die Package: <input type="checkbox"/>					
Config: 256M x 64		Env. Code RoHS					
DRAM: Elpida		Bank: 2					
DRAM Part #: EDJ1108BBSE-DJ-F rev B		Assembly Type: Single Board/Non Stacked					
PCB Part: 2025403-0F1.A00 rev A, R/C B rev 0		DDR3 DIMM					
PCB_layer_count: 6 Layer							
Module Info: Unbuffered Non-ECC 1333MHz							
SYSTEM INFORMATION		TESTING DETAILS					
MINIMUM SYSTEM INFORMATION		55°C Temperature: Standard Voltage					
Minimum System:	DX48BT2	Start Date:	9/17/2009				
Serial Number:	BQBQ8070001Y	Stop Date:	9/21/2009				
Board Revision:	E26191-201	Insertion Test:					
Post Memory Count:	4096MB	SPD Check:	Pass				
Processor Code:	Intel® Core™2 Duo,E8500,3.16GHz,1333	MCFT Min:	Pass				
Bios at time of test:	BTX3810J.86A.1893	MCFT Max:	Pass				
MCFT Memory Count:	4G 768M	S3 Test:	Pass				
Max_HDD_Man:		Power Cycle Test:	N/A				
Max_HDD_Cap:		Power Cycle Time:					
Max_HDD_Ser:		OS:	N/A				
MAXIMUM SYSTEM INFORMATION		Service Pack:	N/A				
Maximum System:	DX48BT2	Test Version:	R.S.T PRO3 v3.02				
Serial Number:	BQBQ80700011						
Board Revision:	E26191-201						
Post Memory Count:	8192MB						
Processor Code:	Intel® Core™2 Duo,E8500,3.16GHz,1333						
Bios at time of test:	BTX3810J.86A.1893						
MCFT Memory Count:	8G 768M						
Max_HDD_Man:							
Max_HDD_Cap:							
Max_HDD_Ser:							
VENDOR CONTACT INFORMATION							
Contact:	Contact Phone:	Purchase Order #:					
Mike Mohney	714.424.3976						
Test Traveler Notes:			CMTL USE ONLY:				
			Verified by:				
			Emailed by:				

Test Technician: Thanh Nguyen

In the event of a module failure, CMTL is not required to provide root cause analysis. Accuracy of testing is restricted to the above mentioned module with specific DRAM, PCB and other components as listed and tested with the CMTL Memory Compatibility, Functionality Test, Microsoft Advanced Server 2000®, Windows NT 4.0 Enterprise Edition®, Windows XP®, Windows 98 SE®, Dos 6.22®, MSTRESS® (v x.x), XLINEAR® (v x.xx), FXLINEAR® (v x.xx), Patin® (v x.x), WinMTA® (v x.xx). (Voltage margining applied only to those systems that are applicable.)

WWW.CMTLABS.COM